



















- |          |        |      |
|----------|--------|------|
| <b>A</b> | 4x45   | x 16 |
| <b>B</b> | 1.4x25 | x 36 |
| <b>C</b> | 3x25   | x 69 |
| <b>D</b> | 6x50   | x 4  |
| <b>E</b> | 3x20   | x 16 |
| <b>F</b> | 4x30   | x 5  |






12 18



14  
22  
21  
13.1  
15  
16  
9  
8  
6  
7  
20  
11

№	Image	PCS			
			mm	mm	mm
1		2	19	52	1800
2		44	19	92	1300
3		42	19	92	284
4		21	19	92	1800
5		1	40	70	1795
5.1		1	40	70	1795
6		1	40	70	1320
7		2	15	15	480
8		2		305	1800
9		1	40	60	1300
10		4	15	35	1800
11		1		582	1754
12		1		582	1754
13		2	OSB	800	1040
13.1		2	OSB	500	1040
14		8	15	35	1020
15		4	13	92	1060
16		2	15	75	145
17		2	OSB	35	1300
18		1	27	35	1180
19		2	15	35	1300
20		2	15	15	500
21		1		1000	2200
22		1		500	2200
23		1			
24		6			
25		6			
26		1			
27		2			


1



2



3





4

Int.


Ext.

Int.




9


10



C x8




$$a=b$$



6


14-16mm



14-16mm

25





24





12

11


7







Ø12

C x8



27

9





10

B x24

22


21



14



C x16


19






12

MAX  
30 kg/m<sup>2</sup>



16



B x4